


Water flowing through cutless bearings but not reaching coupling even with 50% of packing removed

Theory is brass coupling is so tight inside stuffing box then when shaft is turning and temperatures inc

Plan is to remove brass coupling and machining the IML or inside about 1/64"



Transmission

and nuts loose.

crease not enough water is passing over shaft