

Work Order No: 15844

Part Number	Description	Bin	Qty	Price	Ext Price
INJECTOR REBUILD			12	250.00	3000.00
11994	GASKET		34	0.89	30.26
20707685	PLANE GASKET		2	7.94	15.88
21624740	FUEL FILTER		2	38.40	76.80
3501530	GASKET		2	8.22	16.44
842913	SEALING RING		2	10.59	21.18
858659	HOSE CONNECTION		4	52.77	211.08
859002	GASKET		6	5.60	33.60
948685	CAP NUT		24	2.67	64.08
953036	STUD		22	5.80	127.60
955893	WASHER		24	0.37	8.88
957171	GASKET		24	0.53	12.72
966978	V-BELT		2	64.23	128.46
967944	O-RING		2	3.43	6.86
969011	GASKET		4	2.19	8.76
969299	HOLLOW SCREW		2	10.44	20.88
984725	FLANGE SCREW		4	0.52	2.08
984727	FLANGE SCREW		2	0.59	1.18
994559	HOSE CLAMP		4	2.61	10.44
997641	SHUT-OFF COCK		2	29.39	58.78
3582599	INSERT		2	3546.84	7093.68
23557470	GASKET		2	36.76	73.52
951930	SPRING PIN		2	1.11	2.22
21325765	V-CLAMP		2	41.60	83.20
3582310	FEED PUMP		2	177.23	354.46
3582639	SEALING STRIP		2	32.71	65.42
466328	HOSE		2	19.86	39.72
838864	V-CLAMP		2	6.84	13.68
844093	FLANGE		4	34.09	136.36
845646	FUEL HOSE		4	118.69	474.76
847573	SEALING STRIP		2	31.20	62.40
858979	SEALING RING		2	22.54	45.08
859052	GASKET		2	5.46	10.92
859963	EXHAUST PIPE ELBOW		2	543.37	1086.74
860448	FUEL PIPE		2	79.69	159.38
860920	GASKET		4	31.73	126.92
861260	TURBOCHARGER		2	3859.06	7718.12
861657	HOUSING		2	463.84	927.68
864723	SEALING RING		2	13.59	27.18
876579	CONVERSION KIT		2	338.20	676.40
CRC06020	DEGREASER NON-CHLOR		1	22.29	22.29
SCP23386	MARINE CLMP #16 1/2 BAND		4	1.70	6.80
MLM32012	3/8H X 1/4P MALE HOSE BARB		2	2.59	5.18
INJ0375	BLUE SILICONE HOSE		4	3.75	15.00
60113666	FLANGE SCREW		2	2.71	5.42
201	CONVENTIONAL 50/50 ANTIFREE		10	17.25	172.50
SHIPPING			1	150.00	150.00
SHOP SUPPLIES			1	75.00	75.00
				Material:	23485.99

Date	Description	Hours	Price
08/25/2020	204 LABOR	0.75	101.25
08/31/2020	210 LABOR	5.45	735.75
09/01/2020	210 LABOR	4.25	573.75
09/23/2020	210 LABOR	8.00	1080.00
09/24/2020	210 LABOR	7.50	1012.50
09/25/2020	210 LABOR	4.00	540.00
09/28/2020	210 LABOR	5.00	675.00

Work Order No: 15844

10/06/2020	210	LABOR	7.50	1012.50
10/07/2020	204	LABOR	1.50	202.50
10/07/2020	203	LABOR	1.00	135.00
			Labor:	6068.25
			Subtotal:	\$29554.24

==== 5 : MID-SHIP FLOAT SWITCH (T/M) By: 206
 10/09/2020 -- AT TIME OF BAYTEST, NOTICED WATER ACCUMULATING IN MID-BILGE AREA AS A RESULT OF LEAKING SHAFT LOGS, AND MID-SHIP FLOAT SWITCH INOPERATIVE. REMOVE AND REPLACE FAULTY FLOAT SWITCH AND TEST - OPERATING PROPERLY AT THIS TIME.

Part Number	Description	Bin	Qty	Price	Ext Price
RUL40A	RULE A MATIC PLUS MERCURY F		1	57.39	57.39
SHOP SUPPLIES			1	10.00	10.00
				Material:	67.39

Date	Description	Hours	Price
10/09/2020	204 LABOR	1.00	135.00
		Labor:	135.00
		Subtotal:	\$202.39

==== 6 : PORT ENGINE (T/M) By: 206
 8/17/2020 -- CUSTOMER ADVISES THE PORT ENGINE IS SHOWING LOW OIL PRESSURE AND ENGINE RUNNING HOT, CHECK AND ADVISE.

-- MECHANICAL TEST OIL PRESSURE, OK AT THIS TIME, SUSPECT FAULTY SENDER. REMOVE AND REPLACE OIL PRESSURE SENDER. PORT TEMPERATURE READING INACCURATELY. REMOVE AND REPLACE TEMPERATURE SENDER AND BAYTEST - PORT OIL AND TEMPERATURE READING PROPERLY AT THIS TIME.

Part Number	Description	Bin	Qty	Price	Ext Price
1324492	RELAY		1	25.84	25.84
7737784	INSTALLA.INSTRUCTION		1	3.29	3.29
827151	TEMPERATURE SENSOR		1	85.34	85.34
833927	THERMO MONITOR		1	147.33	147.33
863169	PRESSURE MONITOR		1	81.16	81.16
866833	PRESSURE SENSOR		1	194.47	194.47
873601	CABLE		1	27.43	27.43
SHIPPING	From Vendor		1	25.00	25.00
				Material:	589.86

Date	Description	Hours	Price
10/08/2020	204 LABOR	1.00	135.00
10/09/2020	204 LABOR	2.50	337.50
		Labor:	472.50
		Subtotal:	\$1062.36

Payment:
COD : \$7464.82 Acct # 3722

Shop Supplies \$0.00
\$0.00

Labor & Material \$31313.99
Sub Total \$31313.99
8.625% Tax \$2700.83

Date Brought In 07/21/2020

Total Amount \$34014.82
Less Deposit \$26550.00
Balance Due \$7464.82

Thank you for choosing Dickson's Marine for your service needs.